SAFETY INSTRUCTIONS

WARNING: FAILURE TO COMPLY WITH THESE INSTRUCTIONS MAY RESULT IN SERIOUS INJURY.

SPECIAL PRECAUTIONS

1. Read and understand all instructions and warnings before use.
2. Inspect before use. Do not use if damaged. If any parts are missing, do not use.
3. Examine thoroughly to make sure unit is set up properly.
4. Do not use any components not supplied or approved by Werner Co.
5. Keep fingers clear when opening and closing.

SET UP

1. Rotate legs into position, then lock hinges. See hinge operation label located near each locking hinge.
2. Place work platform on firm level ground. Do not use on slippery surface.
3. Make sure that the installation and use does not violate any federal, state or local codes.
4. Never place anything under or attach anything to unit to gain height or to adjust for uneven surfaces.

USE

1. **DANGER! Metal Conducts Electricity.** Never use near electrical current.
2. Use extra caution near operating machinery.
3. Acids (such as muriatic or hydrochloric) are corrosive to aluminum and can seriously affect strength. Do not expose unit to corrosive substances.
4. Product designed to support the weight of one person and material. Maximum weight not to exceed duty rating (see other labels).

MAINTENANCE

1. Keep platform and legs free from debris and paint build up. Do not allow tools and materials to accumulate on platform.
2. Keep all pivoting connections free from foreign substances.
3. Do not abuse by dropping or impacting.
4. Secure from movement to avoid damage while transporting.
5. Lubricate hinge mechanism regularly.
6. For additional information & instruction contact:
   Werner Co., 93 Werner Road, Greenville, PA 16125, (724) 588-8600

ACCESS

1. Face platform when climbing up or down steps.
2. Always keep body centered between side rails
3. Never climb platform from the side unless secured from sideways motion and tipping.

© 2004 Werner Co.
Rev A 9/04 P/N 63293-01